## **LESSONS LEARNED**

## POV ACCIDENT PREVENTION SAFETY MESSAGE



Over the Veteran's Holiday weekend, four soldiers and two German civilians were riding in a rented five passenger Mercedes-Benz. Preliminary investigation results indicate that, while traveling at excessive speed on a secondary highway, the vehicle approached a slight curve with a posted speed limit of 60 kph. Due to excessive speed, the vehicle drifted past the centerline and struck an oncoming semi-truck headon. Two of the soldiers and both German civilians were killed. The two remaining soldiers received life threatening injuries resulting from the accident. The truck driver was treated for shock. The four passengers in the back seat were not wearing seatbelts.

## **Causal Factors**

- Excessive speed.
- Loss of Control. Vehicle crossed the centerline.
- Exceeding vehicle passenger limitations.
- Underestimated personal risk.
- · Seat belts not used.

## **Lessons Learned**

- √ Speed Kills!
- ✓ Buckle your seatbelt!
- ✓ Accept no unnecessary risk!
- ✓ YOU ARE NOT INVINCIBLE!

